

Dear Brothers Assalamu Aleykum;

Per your request, the following is a preliminary summary of cost for the roof top units to be replaced and upgraded per the engineer's study and recommendation

(Note: First Option to replace 7 out of 10 units and second option to replace 10 out of 10 units):

Unit Number	Description	Old Size	Status	New Size	Cost To Replace 7 out of 10 Units with New Per Engineer's Specs	Cost To Replace 10 out of 10 Units with New Per Engineer's Specs
1	Main Prayer Hall/Men & Women	15 Ton	Damaged By Hail	25 Ton VAV	\$55,000	\$55,000
2	Main Prayer Hall/Men & Women	15 Ton	Damaged By Hail	25 Ton VAV	\$55,000	\$55,000
3	Basement-Old Phase	7.5 Ton	Damaged By Hail	7.5 Ton VAV	17,500	17,500
4	Main Lobby- Old Phase	5 Ton	Old Unit-Cracked Burner	7.5 Ton VAV	17,500	17,500
5	Multi-Purpose Room-New Phase	25 Ton	Damaged By Hail	25 Ton VAV	\$55,000	\$55,000
6	Multi-Purpose Room-New Phase	12.5 Ton	Damaged By Hail	15 Ton VAV	\$40,000	\$40,000
7	Multi-Purpose Room-New Phase	7.5 Ton	Seems OK-Needs Custom Hail Guard		-	\$17,500
8	Offices-New Phase	4 Ton	Seems OK-Needs Custom Hail Guard		-	\$10,000
9	Offices-New Phase	3 Ton	Seems OK-Needs Custom Hail Guard		-	\$7,500
10	Basement-New Phase	8.5 Ton	Damaged By Hail		\$20,000	\$20,000
	Master Controls/Misc.				\$25,000	\$30,000
	Total				\$285,000	\$325,000

In addition, you have asked me to provide a cost to isolate the "Wash Room" with it's own RTU and an Exhaust Fan as well as to repair/cover the concrete roof with a membrane and fix the drain:

Description	Cost
RTU (2 Ton) + Curb	\$6,500
Exhaust Fan	\$2,500
New Roof over Concrete	\$5,000
Electrical/Plumbing/Misc	\$3,500
Total	\$17,500